










8134



















8134N



8134F

NR	ELEMENT	8134N
E1		1
E2		1
E3		
E4		1
E5		4
E6		1
E7		1

NR	ELEMENT	8134F
E1		1
E2		1
E3		1
E4		
E5		
E6		
E7		1



				8134N	8134F
Nr	Element			Σ	Σ
5		DIN 985	M10 (OC)	3	3
30		DIN 9021	8x24	24	
31		DIN 985	M8 (OC)	16	
61		-	KL105 (OC)		4
103		DIN 9021	10x30	3	3
145		DIN 603	M10x30 (OC)	3	3
190		-	K_B_1	1	1
193		DIN 603	M8x20 (OC)	8	
209		DIN 933	M8x35 (OC)	8	
213		-	Z_NA_1	1	1
214		-	Z_NA_2	1	1

8134N

8134F


ENG: „Due to the irregular shapes of natural robinia wood trunks, all dimensions provided in the documentation may slightly vary from the actual dimensions of the product.”

PL: “Z uwagi na nieregularne kształty naturalnych pni drewna robinii, wszystkie wymiary podane w dokumentacji mogą nieznacznie odbiegać od rzeczywistych wymiarów produktu.”




1

8134N




INST_5000




1

8134F





INST_5000




2

8134N





2

8134F




3

8134N





"0"




3

8134F



Nr	Element			Σ
61		-	KL105 (OC)	4




I




II




III




IV



V





VI



4

8134N
8134F

Nr	Σ	Element		
213	1		-	Z_NA_1
214	1		-	Z_NA_2

