




















8188




8188N

NR	ELEMENT	8188N
E1	 D8188_1N	1
E2	 D8188_2N	1
E3	 D8188_3N	1
E4	 D8188_4N	1
E5	 D8188_5N	1
E6	 D8188_6N	1

NR	ELEMENT	8188N
E7		1
E8		1
E9		1
E10		2
E11		1
E12		2

NR	ELEMENT	8188N
E13		1
E14		1
E15		1
E16		1
E17		1



8188N



8188




ENG: „Due to the irregular shapes of natural robinia wood trunks, all dimensions provided in the documentation may slightly vary from the actual dimensions of the product.”

PL: “Z uwagi na nieregularne kształty naturalnych pni drewna robinii, wszystkie wymiary podane w dokumentacji mogą nieznacznie odbiegać od rzeczywistych wymiarów produktu.”




1

8188N






2

8188N






INST_81_16P
INST_81_2
INST_81_72
INST_81_45



3




8188N



4



8188N

INST_81_45




5

8188N





6

8188N



INST_81_16P
INST_81_185
INST_2038_1
INST_Z_1



7

8188N

B25 0,92m³

min. 48H

